


Fault type	Condition for Fault	Observable Symptoms	Possible cause
P0601 FTB 41	• Internal fault in control unit.	• None.	• A174: Aftertreatment Control Module (ACM).

Action:

Conform the internal fault in Control unit.