


Fault type	Condition for Fault	Observable Symptoms	Possible cause
P241E FTB 00	• AdBlue temperature too low.	• Possible engine de-rate.	• Mechanical fault. • Damaged or restricted actuator coolant lines. • Tank heater valve.

- Visual check the Aftertreatment AdBlue tank heater valve Coolant hose for faults.
- Check coolant inlet and outlet lines for signs of damage that could cause poor coolant flow to the actuator.