


Fault type	Condition for Fault	Observable Symptoms	Possible cause
P020A FTB 25	• Unexpected electrical response.	• Power loss.	• Injector 1. • Worn injector.

Check and replace the Injector.