
P0219 - Engine overspeed condition



Fault type	Condition for Fault	Observable Symptoms	Probable cause
P0219 FTB00	• Engine speed too high.	• Unit injector, cut-out.	• Wrong gear may be engaged (when engine braking). • The engine is running on engine oil.

Action:

- Check for oil leakage in the turbo charger.
- Check the closed crankcase ventilation.