


Fault type	Condition for Fault	Observable Symptoms	Possible cause
P208A FTB 13	• Open circuit.	• No AdBlue solution dosage.	• Wiring harness. • Open circuit, Control wire (-). • Aftertreatment AdBlue pump. • Aftertreatment Control Module (ACM).

Resistance Measurement:



Measuring	Key position	Measurement points		Reference value	Measured value	Other (Special tool No.)
		Breakout box	Wiring diagram			
Open circuit Check	Off	20 – 47	A174.A:20 – M49:1	R = 0 Ω – 5 Ω		88890074, 9990014, 9998699